

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-12988

INITIAL CUSTOMER ORDER NO.

ATTN: DENNIS SANITA

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/13/94

04/14/94

05 7-69

6255392

700 30-06

ADL

ACCESSORIES

L/SIGHTS

L/STUDS

FROM:

BROWN, RAY
101 SUNSET
HEWITT

TX 76643

SHIP TO:

BROWN, RAY
101 SUNSET
HEWITTTX
76643

CUST NO: 095911 G.L.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER NC

059015

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRIED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

E1

TRIGGER GROUP

B2

E2

BOLT ASSY.

B3

E3

BARREL ASSY.

B4

E4

REC. ASSY.

B5

E5

WOOD

C1

D1

METAL

C2

D2

MAIN FAULT

We could not duplicate customer concern, however, I suspect that there is a fault under one of the trigger assembly components. Suspect has been removed from our inspection, indicating it was then sent back to customer. Under suspicion, he stated he bought rifle in May 1994 and has been having trouble with it since.

Replace trigger assembly component

Truly is a great job of good work, I agree to replace trigger assembly component & clean the rifle. Explained to Mr. Brown that we would have a repair charge for the labor involved.

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94