



RECEIVING AND ESTIMATING REPORT

DATE		DATE CODE		COMMENTS	JIM STEKL "B"	
01-31	07/68	01-31	07/68	SERIAL NUMBER	MODEL AND GRADE	001
ACCESSORIES				1-0091981	700	R
ORDER				72-1402		

FROM:

SHIP TO

ACCOUNT NUMBER
063163
REPAIR CHARGE
40.00

01-007972-3
01A 7331235

ESTIMATE
6.3388

TAX ST
TAX LTY

QUANTITY

4.09

\$ 440

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☒ VERY WORN

☐ MISUSED

☐ QUOTE

CUSTOMER'S COMPLAINT

"Gun fired when pressure built, then it was full"

MAIN FAULT

Stock Marvel -

Trigger assembly was not properly adjusted and disassembled -
Trigger pull 6 1/2", was very heavy, not enough resistance
insufficient resistance adjustment screw turned to

PARTS

443 Trigger assembly R.C.C. could not be adjusted Trigger assembly
to reset trigger assembly - make
adjustment and test - if
necessary replace trigger
assembly and test

42 cuts

polished Chamber
Check Headings

FOR COMPUTER REF ONLY

ESTIMATE

DEPARMAN

ML

74A

J