

~~Missouri~~
Barrett
Larson
Sperling
Preiser
Chinnall
Sanita

This gun goes off
when I am getting it unloaded
it has not had a twisted
windshield so far.

respectfully
Bob Buckley

Re:1

Jail
Sanita

ALL CLAIMS AND RETURNED GUNS MUST BE ACCOMPANIED BY THIS BILL

RECEIVED BY _____

Examination has been completed on your Model 700 ADL 243 Win.
caliber rifle, serial number 6883146, which you returned to us
when it allegedly went off when opening it to unload.

The returned firearm, which was produced in November of 1975,
has been examined by our firearms experts, who report that it
contained our high-pressure proof test, gallery test, and final
inspection stampings, indicating that it had successfully passed
all our necessary tests prior to shipment.

The general condition of the gun appeared to be fair and it was
noted that the stock contained mars; there were mars on the metal,
and the toe of the stock was chipped. In addition, when the bar-
reled action was removed from the stock, a considerable amount of
dust and dirt was noted in and around the trigger assembly and on
the bottom of the receiver. In going over the individual parts,
we found the headspace normal, recoil shoulders normal, and chamber
rusty.

Examination of the rifle and trigger assembly could not duplicate
the incident that was described. All parts tolerances and dimen-
sions were found to be normal, including sear-connector engagement.
Also, factory seals were intact on the trigger adjusting screws,
indicating no alterations were made on the trigger outside our
company. Trigger pull was within our specifications at 5½ pounds.

Based on our findings, Remington Arms Company, Inc., cannot accept
any liability or responsibility for the incident. We can only as-
sume that accidental contact was made with the trigger, with the
safety in the "fire" position, which caused the rifle to fire, or,
that foreign matter getting inside the trigger assembly caused in-
ternal parts to hang-up and resulted in the accidental firing.