

4-8-94

DEAR SIR,

IN MY ORIGINAL LETTER TO REMINGTON, I  
STATED THAT THIS RIFLE HAS A TENDENCY TO  
ACCIDENTLY DISCHARGE ON OCCASION WHEN TAKING  
OFF THE SAFETY.

THIS GUN IS USED VERY LITTLE, MOSTLY IN  
LATE FALL AND WINTER WHILE PREDATOR CALLING.  
THE ACCIDENTAL DISCHARGES SEEM TO OCCUR  
WHEN THE RIFLE HAS SAT DORMANT FOR LONG PERIODS  
OF TIME AND ALWAYS WITH THE VERY FIRST  
ROUND CHAMBERED.

I HAVE JUST RECENTLY TAKEN THE BLUING  
OFF THIS RIFLE BECAUSE IT WAS BADLY WORN. I  
FOUND OUT THAT IT IS STAINLESS AND CAN'T GET IT  
REBLUED LOCALLY.

Dennis Button  
13860 Delbete Road  
Albion, N.Y. 14411

MODEL 700 17 CAL.  
SERIAL No 6445063

OFFICE COPY

DATE

DATE

DATE

PATTERN

RD6025 REV. 1/84