

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-07518

INITIAL CUSTOMER ORDER NO.

FJR

VCI F. Supply

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

02/22/94

03/02/94

8/82

R6405822

700 30-06

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

BYRNE, PATRICK F
PO BOX 281
CLUM HILL RD
TANNERSVILLE

NY 12485

BYRNE, PATRICK F
PO BOX 281
CLUM HILL RD
TANNERSVILLE

NY
12485

CUST NO: 093225 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

Product Service

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1					
TRIGGER GROUP						
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4				F3
REC. ASSY.		B5		D2	E4	F4
WOOD			G1	D3	E5	F5
METAL			C2			

MAIN FAULT

Mfgn Aug 82 Bolt stop stuck, sear stuck and trigger was stuck as
Received- TRIGGER ASSY gummed up with shellac like substance.
Unable to duplicate customer's concern after cleaning. Trigger
Assy. and the rest of the gun should be cleaned and
maintained in a lightly oiled condition. Suggest having
a qualified gunsmith assist with periodic maintenance.
Exchange trigger Assy. to restore confidence in the rifle.
Strictly as a gesture of goodwill. After cleaning trigger pull
measured 7 lbs.

PARTS

COMMENTS

5am lift measured

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTER

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1

PPS 00832