

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-12944

INITIAL CUSTOMER ORDER NO.

F.P.S.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/13/94

04/13/94

RI 11-00

A6381678

700

300 WIN

MAG/BDL

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

CAMBURN, BOB
1039 WEST AVE
OCEAN CITY

NJ 08226

CAMBURN, BOB
1039 WEST AVE
OCEAN CITYNJ
08226

CUST NO: 095878 E.L.O.B.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☒ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

20.00

COD

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.					E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			
MAIN FAULT						
Left mfg. No 1988 could not duplicate common, however Upon repair, trigger working very sluggish, hammer trigger assembly bound with a heavy greasy substance. But stop does not sticking.						
PARTS			COMMENTS			
			Replace Cooper's trigger assembly with N/S (customer request) and clean action at 1/2 normal cost as per letter of good will			
			JOHNSON			
REPAIRMAN			PROOF	CLEAN	TEST	TARGET
GALLERY TESTER			DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94