

RECEIVING AND ESTIMATING REPORT ✓

TIAL JM		CUSTOMER ORDER NO.		COMMENTS			
TE RECEIVED 1/18/91	DATE OPENED 01/28/91	DATE CODE AZ 3-75	SERIAL NUMBER 6846400	MODEL AND GRADE 700 30-06 BDL		ORDER R 91-02777	
CESSORIES W/STUDS		SCOPE BASE					

OM: CAMPBELL, WILLIAM L
HC 66 BOX 266B
FERRIDAY LA 71334

SHIP TO: CAMPBELL, WILLIAM L
HC 66 BOX 266B
FERRIDAY LA 71334

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 2-8-91	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	---------------------	------------

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
------------	-----	-----------	-----	-------------	-------

IN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST: Gun fired when Bolt was closed.

N FAULT: Trigger assembly contaminated with sticky, gummy residue. Internal trigger parts are gummed and not moving properly. Semi-auto won't strike to side plate of trigger housing. Bolt release is sticking and not operating properly. Outside of trigger assembly and return of action wet with excessive oil(?)

Send quotation to clean present trigger assembly, if possible. If not possible, we can install a new trigger assembly at ± normal cost, as a gesture of good-will.

REPAIRMAN RBA	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 00864