Remington Arms,

31

1

I am returning this Remington Model 700, .30-06 caliber rifle, # 6846400 for your inspection. Please contact me after you have inspected this gun and located the problem.

On my last hunting trip, about ten days ago, I had a very disturbing thing happen. I entered my stand and proceeded to load my rifle. I layed the barrel across a rest and inserted three bullets into the bottom of the gun. I moved the bolt forward advancing the first bullet into the chamber. When I moved the bolt forward and locked it down the gun fired, I never touched the trigger, I simply advanced the bolt. The shot went directly over the top of my hunting partners jeep.

This gun was given to me by my parents as a gift in 1975 and I have only hunted with it about 10 or 15 times. I realize how dangerous this weapon is in it's current conditon and cannot imagine that any gun, at any age, could do this.

Sincerly,

William L. Campbell HC 66 Box 266B Ferriday, Louisiana 71334

(318) 757-2638

1-11-1991

PPS 00865

7/90

IXY X