

~~CONFIDENTIAL~~

R-16-01 107

allison Carey ^{serious} PT
alleged follow down - Dos

frig + rear worked on
+ frig - light + lots of overtravel
↳ 2 1/4 lb pull - way below
Rev spec.

.065" rear lift - good + w/inspec.

Overtravel + pendage adjustment
screws backed out of frig main

all frig components are correct w/
no defects. However, the
base + frig overtravel
specs have been adj. out back
of spec.

Overtravel adjustment of spec.

Results as above.

Not found

all parts to be for base + frig
+ base + frig overtravel of spec.