

TO Remington Arms Service
14 Hoefler Avenue
Ilion, New York 13357

CARL'S RELOADING CENTER

435 East 3rd North
RICHFIELD, UTAH 84701
Phone (801) 896-6871

SUBJECT: Gun Repair

DATE: 5/21/91

FOLD ↑ My customer claims that the enclosed TOO BOL
243, SN 6400232, fires when the safety is moved
to fire. This happens on ^{very} rare occasion.

I am afraid of this gun so I am sending
it to you for factory testing and adjustment.

Sincerely,

PLEASE REPLY TO

SIGNED

Carl J. Thurgood

REPLY

DATE:

SIGNED

Item # F270 Grayard, P.O. Box 2944, Hartford, CT 06104-2944
© Wheeler Group, Inc., 1982

THIS COPY FOR PERSON ADDRESSED

steam rifle or, we can install a new
trigger assembly at $\pm$ normal cost,
as a gesture of good-will, if it will
better restore confidence in the
rifle.

REPAIRMAN

GALLERY TESTER

PROOF

DATE

CLEAN

DATE

TEST

DATE

TARGET

DATE

PATTERN

DATE

OFFICE COPY

RD6925 REV. 7/90