

Dear Sir:

Would you please check the Remington
700 ADL Serial# A6480720, it discharged
after the bolt was being closed.

Thank you
Rod Carney

ORDER
R91-23431

STEKO

ADL

TERS SUPPLY
WINING RD
NY
13662

DATE	VIA
2/1/77	UPS
REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

INSPECT

1	ins
2	
3	
4	
5	

possibly however
it has been a few
screws - W. Thayer
Kianit.com - Travel

and re - seal
by 07, if owner
will a new
normal cost
- will if it broke
leave the right

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
127					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91