

NO. 700
 2. NO. 6259346
 3. 1-6-83
 4. BY L. C. Beckman
 5. ✓

R# C1224
 P.T. N.
 MFD. 7-69

6-20-83

COMMENTS:

THIS GUN WAS COCKED, ITS SAFETY WAS SWITCHED TO THE POSITION, AND IT WAS PLACED INSIDE A COLD BOX (INSIDE THERMOMETER INDICATED -30°F) AT 4:35 a.m. ON 06 APRIL 83. UPON REMOVAL OF THIS GUN FROM THE COLD BOX (INSIDE THERMOMETER INDICATED -29°F) AT 9:40 a.m. ON 07 APRIL 83, THE FOLLOWING WAS IMMEDIATELY PERFORMED:

① Pull trigger to see if it binds or sticks back —
 IT DID NEITHER.

② Switch safety to "F" position — IT DID NOT FIRE-DOWN.

③ Oper. bolt and check for same — NONE.

④ Check bolt and work handle — NO PROBLEM. POSITIVE ACTION.

⑤ Switch safety to "S" position, pull back hard on trigger, release trigger, switch safety to "F" position. Repeat this three times. — THE FIRING PIN DID NOT FIRE-DOWN.

⑥ With safety switched to "F" position, pull trigger. — THE FIRING PIN FIRED-DOWN. SNAPPY.

⑦ Rack the bolt and repeat the entire test. — No PROBLEMS ENCOUNTERED AND NO F.S.R. OBSERVED.

⑧ Perform "trick test". — GUN PASSED THE "TRICK TEST".

(	(	(	(	(	(	(	(	(	(
)	)	)	)	)	)	)	)	)	)
(	(	(	(	(	(	(	(	(	(
)	)	)	)	)	)	)	)	)	)