

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 94-06442

INITIAL CUSTOMER ORDER NO.

PPS

DATE RECEIVED  
02/15/94DATE OPENED  
02/21/94DATE CODE  
OF 7-85SERIAL NUMBER  
B6727018

NEW SERIAL NUMBER

MODEL AND GRADE  
700 30-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

CARTERS COUNTRY  
8925 KATY FREEWAY  
HOUSTON

TX 77024

SHIP TO:

CARTERS COUNTRY  
8925 KATY FREEWAY  
HOUSTONTX  
77024

CUST NO: 006829 WILM L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059015

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW  
☒ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

Product Service

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

*Customer would like gun inspected, original custo.  
Complaint was fires on bolt closing - inspect gun, cus.  
said that it happened with new trigger. Also.  
Note: See # in bolt does not match gun  
Mfgn date 7/85 Replacement trigger operates correctly in  
every respect. See # on breech bolt does not match  
owner doesn't know how bolt might have been changed -  
check headspace and proof bolt to gun. Clean action, polish  
top of magazine follower*

PARTS

*\* After talking to customer I think that the snap was the safety  
when released, not the firing pin.  
Trigger pull was 6# as per  
Spec. Lift is .017*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/9

PPS 00934