

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

February 23, 1989

Cast Bullet Shooters Supply
Attn: Ron Oates
170 Upper Flower Cr. Rd.
Libby, MT 59923

Dear Mr. Oates:

Your letter of recent date addressed to our Bridgeport, CT location, referring to a Mohawk 600, serial number 6745607, has been forwarded to my office for handling.

We are conducting a trigger replacement program for certain concerned lots of Model 600 series firearms. The program has been nationally advertised over a period of years and involves complete fire assembly replacement for these rifles at no charge.

If you purchased your Model 600 second hand, the rifle may already have been updated. Therefore, if a "V" stamping appears on the left side of the trigger, the gun has had trigger replacement. If no "V" stamping appears on the left side of the trigger, the rifle requires trigger replacement.

Enclosed for your convenience is a list of Montana Remington trigger replacement stations, or you may return your rifle to our Arms Service Department here at Ilion, NY 13357 for correction.