

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R93-10614

INITIAL CUSTOMER ORDER NO.

PS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

ACCESSORIES

W/STUDS

B6814615

700 30-06

BDL

FROM:

CHapel SPORTS  
116-20 ATLANTIC AVE  
RICHMOND HILL

NY 11419

SHIP TO:

CHapel SPORTS  
116-20 ATLANTIC AVE  
RICHMOND HILL

NY

11419

CUST NO:004292 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW  
☐ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
| CYCLE            | A1   | B1       |        |          |     |         |
| TRIGGER GROUP    |      | B2       |        |          | F1  |         |
| BOLT ASSY.       |      | B3       |        |          | F2  |         |
| BARREL ASSY.     |      | B4       |        |          | F3  |         |
| REC. ASSY.       |      | B5       |        |          | F4  |         |
| WOOD             |      |          | C1     |          | F5  |         |
| METAL            |      |          | C2     |          |     |         |

MAIN FAULT

Could not duplicate concern. However, upon receipt rifle bolt  
stop action and trigger components working properly. Examination  
revealed heavy, sticky, opening resistance coming action, trigger pull  
and bolt stop action.

PARTS

Upper Pulley - 6/4 lbs  
Bolt - .013

COMMENTS

Replace component trigger assembly  
and clean action at 1/2 normal  
operational cost, as quality of good  
work.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92