

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL FPS	CUSTOMER ORDER NO. 75325				
DATE RECEIVED 05/08/91	DATE OPENED 05/08/91	DATE CODE KY 5-74	SERIAL NUMBER 6741954	MODEL AND GRADE 700 308 WIN BDL	ORDER R 91-1055
ACCESSORIES W/STUDS		L/SIGHTS			

FROM:	SHIP TO:
CHARLIES SPTG GOODS 7401 H MENAUL N E ALBUQUERQUE NM 87110	CHARLIES SPTG GOODS 7401 H MENAUL N E ALBUQUERQUE NM 87110

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	-------------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

SUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *"Customer said fired while on safe - when he bumped gun"*

MAIN FAULT *Cannot duplicate complaint, however, trigger assembly has been completely mis-adjusted outside of factory - foreign sealant on all adjusting screws: 1) trigger pull follows min 2.5, # 2) insufficient rear engagement 3) excessive over-travel. Seal lift 0.1" @ 0.005"*

ARTS	<i>Since rear engagement has been altered outside of factory, send quote for new trigger assembly at 1/2 normal cost as gesture of good will.</i>				
REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD0925 REV. 7/90