

M/700 Customer Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700

GENERAL CONDITION: NEW R # : 013812

OUTSIDE WORK: SCOPE MOUNTED DATE: 7-12-72

FROM: CHRISTMAN'S INC.  
DARIEN, CT.

FIRED AMMO TYPE: REMINGTON

& CONDITION: \_\_\_\_\_ GUN # : 6394467

PROOF: R.E.P.- ASSEMBLER 97 INSP.: 74 TEST: \_\_\_\_\_ CODE: XT = 12/70

HEADING: O.K. GR./CAL.: 222

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_

CHAMBER: O.K. APPROVED: \_\_\_\_\_

TEST: 10 ROUNDS - O.K. APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

CONNECTOR - SEAR ENGAGEMENT .010 (MIN. IS .020) TRIGGER  
PULL = 2LBS. (MIN. IS 3LBS.) NECK MEASURES .460 (MIN. = .4518)  
THROAT IS SHALLOW.

COMPLAINT: "CHAMBER NECK IS TOO SHORT, CHECK TRIGGER AT LIGHT SETTING"

INCIDENT: POTENTIAL FOLLOW DOWN.

COMMENTS: THIS RIFLE WAS RETURNED QUESTIONING THE FRONT OF THE CARTRIDGE CASE BEING MARKED, WHICH IS THE MARK OF THE CASE WIPING ACROSS THE RECEIVER IN BEING EJECTED. THE LIGHT TRIGGER PULL AND UNDER MIN. ENGAGEMENT COULD HAVE LED TO A MORE SERIOUS COMPLAINT LATER.