

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

October 7, 1988

Mr. Dennis L. Clark
2514 Radcliffe Drive
Arlingotn, Texas 76012

Dear Mr. Clark:

Examination has been completed on the Model 700 ADL 243 Win caliber rifle, serial number 6327072, which you returned to us because it "discharged as I closed the bolt".

The returned firearm, which was produced in April of 1970, was found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all our necessary tests and inspections prior to shipment from our factory.

The general condition of the gun appeared to be very good, however, it was noted that the stock contained numerous mars and scratches. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the malfunction you reported. All tolerances and dimensions were found to be normal. Also, factory seals were in tact on the trigger adjustment screws, indicating no alterations were made to the trigger adjustments outside our factory. Trigger pull was measured to be 4 1/2 pounds, and sear lift with the safety in the "on-safe" positions was well within specifications at .010".