

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

DEAR MODEL 700 SERIES ARMS SERVICE CUSTOMER:

Our records show that between July 29, 1987 and December 11, 1987 the Remington Arms Service Division installed a new replacement trigger assembly in your rifle sent to the factory for service. The attached paperwork confirms this.

As factory installed, your trigger assembly met all Remington tests and standards for reliability and performance that have made Remington trigger assemblies the preferred choice of serious shooters.

However, during routine test firing, Remington discovered the possibility that an improperly manufactured trigger part may have been assembled in a number of Model 700 series trigger assemblies made and shipped between the above dates. Although unlikely, the improperly produced part could possibly break and allow the rifle to fire when the safety is moved from the safe position to the fire position without the trigger being pulled.

Since the safety and quality of our firearms and firearms parts is our utmost concern, Remington will, at no charge, replace the trigger assemblies in all rifles which possibly contain the impacted part. To accomplish this, a trigger assembly replacement program has been instituted to change triggers in all affected rifles.

Therefore, we request that you promptly return your rifle, via United Parcel Service, transportation C.O.D., to:

Remington Arms Company, Inc.
Arms Service Division
Attention: Jack Kast
14 Hoefler Avenue
Ilion, NY 13357

It is important that you include a copy of this letter along with the attached Arms Service paperwork in the package with the rifle. Remington will then, at no charge, replace your trigger assembly and return the rifle to you, prepaid.