

RECEIVING AND ESTIMATING REPORT

INITIAL LJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 1/31/91	DATE OPENED 02/07/91	DATE CODE AR 3-68	SERIAL NUMBER 335193	MODEL AND GRADE 700 30-06 BDL		ORDER R 91-0389	
ACCESSORIES W/STUDS							

FROM: COGNEVICH, LOUIS M, JR 568 W MARLIN CT GRETNA LA 70056	SHIP TO: COGNEVICH, LOUIS M, JR 568 W MARLIN CT GRETNA LA 70056
---	--

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	-----------	------------

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
------------	-----	-----------	-----	-------------	-------

IN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

TOWNER'S REQUEST
If the trigger is pulled prior to releasing the safety, when the safety is released the gun will discharge.

FAULT
Complaint could be implicated. Trigger assembly has been adjusted inside factory. Additionally, trigger parts were coated with a waxy type substance which appeared like solidified lubricant. This combination resulted in the malfunction noted.

*Rifle was replaced by Contact Service, during delay in handling.
 Per phone call to customer 3/28/91, replace trigger assembly at no charge, and gesture of good will.
 Do not charge handling or return shipping*

REPAIRMAN LEW	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY **STKL**