

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 2/26/90	DATE OPENED 01/03/91	DATE CODE	SERIAL NUMBER A6445396	MODEL AND GRADE 700 270 BDL	ORDER R 91-0018c		

ACCESSORIES: L/STUDS CO 4-77 2ND TIME IN

FROM:	SHIP TO:
CONTI, CARMINE P 89 RICCIARDONE AVE TORRINGTON CT 06790	CONTI, CARMINE P 89 RICCIARDONE AVE TORRINGTON CT 06790

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA V412095796
--------------	--------------------	--------------------------------	------------	------------	-----------	--------------------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

STOMER'S REQUEST

"Fixes when safety moved forward"

IN FAULT: *Trigger assembly is rusted - trigger and connector not moving freely on front gun. Disassembly of barrel - action from stock revealed inside side of barrel and receiver have rusted areas. It appears that the rifle became wet in use and was not disassembled for proper cleaning and maintenance.*

Replace trigger assembly at no charge, as a gesture of good-will.

When rifle is returned, please include a copy of the new M/700 owner's manual which outlines proper lubrication and maintenance procedures.

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90