

RECEIVING ESTIMATING REPORT

REV. 10/86

Remington.

REMINGTON ARMS COMPANY, Inc.

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS

ILLION, NEW YORK 13357

PAGE 1

11/20/89

DATE:

RTS: (315)895-7493. REPAIRS: (315)895-7791

SOLD TO

SHIPPED TO

REPAIR ORDER NO.

REPAIR ORDER NO.: 8925770

8925770

CARMINE P CONTI
89 RICCIARDONE AVE
TORRINGTON CT 06790

CARMINE P CONTI
89 RICCIARDONE AVE
TORRINGTON CT 06790

WE ACKNOWLEDGE RECEIPT OF THE ITEM(S) DESCRIBED BELOW.

THE NECESSARY CORRECTIONS ARE BEING PERFORMED WITHOUT CHARGE AND PREPAID SHIPMENT WILL BE MADE IN ABOUT 4 WEEKS.

WE KNOW YOU WILL FIND THE REPAIR TO BE COMPLETELY SATISFACTORY AND IF WE CAN HELP YOU IN ANY OTHER WAY, PLEASE LET US KNOW.

1700 0270WIN 3DL SERIAL NUMBER: A6445396

CUSTOMER REQUEST:
FIRES WHEN SAFETY MOVED FORWARD

MAIN FAULT FOUND:
EXCESSIVE LUBRICATION IN TRIG ASSE.

1 0026345 TRIGGER ASSEM RH
EXCESSIVE LUBRICATION FOUND ON TRIGGER ASSEM AND ACTION.
COULD NOT DUPLICATE ALLEGED COMPLAINT. REPLACE TRIG ASSEM
AT N/C AS A GESTURE OF GOODWILL. APPROVAL BY MR CONTI PER
PHONE 11/16/89.
NOTE: TEST W/SLAVE STOCK- CUSTOMER HAS REPLACEMENT, HE IS
AWARE THAT STOCK RETURNED IS CRACKED.
CLEAN, TEST
*

TOTAL REPAIR CHARGE
TAXES

INSURANCE
PARCEL POST

TOTAL
CHARGES

NO CHARGE

ATTN

DATE

1925 REV. 7