

In future use, we strongly advise that oil be used sparingly on the firearm and not let accumulate in or on the trigger assembly, as this condition could adversely affect the operation of the trigger assembly.

Since we found the firearm to be completely correct and to function normally in every respect, we are prepared to return it to you in its present condition. However, if you desire, we will install a new trigger assembly at no-charge, as a gesture of good-will, if it will restore confidence in the rifle. We will await the decision and reply.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Sincerely,



D.J. Sanita
Product Service

DJS:tpp

Remington Arms Company, Inc.