

PS 1564

J. S.

RECEIVED

DEC 20 1984

J. A. STEKL

To Whom It May Concern:

I'm writing in regard to a problem with my gun. On Nov. 17th 1984 I went deer hunting in Wisconsin with my Remington rifle, model 700 Bolt action 308 #6469972. I was loading the gun, inserted one bullet in the chamber, and positioned the bolt down. The gun went off barely missing my friend. I jumped and dropped the gun on the ground. My friend asked me what happened. I told him and he said try it again. I inserted another bullet in the chamber, positioned the bolt down into place and again the gun went off. I never touched the trigger. I looked at the gun and noticed the stock was broken from the back of the bolt all the way to the trigger going down to the left. I returned to camp, emptied the chamber and