

*Customer Complaint*

P.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_

MODEL: 700 BDL VAR.

GENERAL CONDITION: NEW

R #: 12943

OUTSIDE WORK: NO

DATE: 6-29-71

FROM: H.P. COX  
MEEK HIGH SCHOOL  
ARLEY, ALABAMA

FIRE AMMO TYPE: -

GUN #: 6403250

& CONDITION: \_\_\_\_\_  
ASSEMBLER 90

PROOF: R.E.P.-C INSP.: 9 TEST: 49

CODE: LU=2/71

HEADING: O.K.

GR./CAL.: 223

BREECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: \_\_\_\_\_

CHAMBER: O.K.

APPROVED: \_\_\_\_\_

TEST: 40 ROUNDS, REMINGTON

APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: \_\_\_\_\_

SEAR AND TRIGGER CONNECTOR COINERS BROKEN OFF,  
ENGAGEMENT P.015 (.005 UNDER MIN.) FIRING PIN POINT  
RADIUS TOO LARGE.

COMPLAINT: FIRED ON CLOSING, FIRED WHEN SAFE WAS PUSHED  
OFF, PIERCED PRIMERS.

INCIDENT: FOLLOWED DOWN.

COMMENTS: THE PRIMER PIERCING WAS NOT DUPLICATED IN TEST-  
ING. IT MAY HAVE SPEEDED UP THE CONNECTOR - SEAR  
BREAK-DOWN