

Remington.



000.111111 0-1-11
R88-35232
hold for reply
Bill Ericson

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

January 31, 1989

Mr. Ralph Cummings
P.O. Box 809
406 Roanoke St.
Christiansburg, VA 24073

Dear Mr. Cummings:

Examination has been completed on the Model 700 L.H. BDL 30/06 caliber rifle, serial number B6367915, that you returned covered by your letter of December 6, 1988 with the complaint that it discharged as I went to lift the bolt to unload.

The returned firearm, which was produced in August of 1986, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests prior to being shipped from our factory.

The general condition of your rifle appeared to be good. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the malfunction that you reported. Many attempts were made to cause the rifle to fire upon bolt opening without success. Factory seals were intact on the trigger adjusting screws, indicating that no adjustment had been made to the trigger assembly outside our factory.