

RECEIVING AND ESTIMATING REPORT

COMMENTS

*Sanita*

ORDER R 93-12836

CUSTOMER ORDER NO.

RECEIVED 28/93	DATE OPENED 06/02/93	DATE CODE R1-76	SERIAL NUMBER A62528-4	NEW SERIAL NUMBER	MODEL AND GRADE 700-22-250	BDL/VAR
-------------------	-------------------------	--------------------	---------------------------	-------------------	-------------------------------	---------

SERIES W/SLODS SCOPE BASE

*Stupple*  
DALES GUNS  
9861 DYER ST 7  
EL PASO TX 79924

SHIP TO:  
DALES GUNS  
9861 DYER ST 7  
EL PASO TX 79924

CUST NO: 029576 C.O.D.L

INVENTORY NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
------------------	--------------------	--------------------------------	------------	-----------	------------

CONDITION	REPAIR CHARGE <i>25.00</i>
SLIGHTLY WORN	EXCISE
DIRTY	TAX
REPAIRABLE	INSURANCE
REPAIRED	UPS
	PARCEL POST
	TOTAL

COMPLAINT	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
E	A1	<i>refle discharges when the safety is disengaged.</i>					
TRIGGER GROUP		B2			E1	F1	
ASSY.		B3			E2	F2	
EL ASSY.		B4		D1	E3	F3	
ASSY.		B5		D2	E4	F4	
			C1	D3	E5	F5	
			C2				

*Upon receipt trigger loose, would not retract. Examination indicated trigger spring, gummy substance on action, bolt stop spring, and trigger assembly. Trigger adjustment screws appear to have been tampered with and replaced. Trigger pull below minimum spec. Left July 1996*

*Trigger pull - low 2 lbs  
in left - .010*

*Replace complete trigger assembly at 1/2 normal replacement cost, in gutters of good unit. Clean action*

*Go ahead per phone 7/16/93 Mr. Bennett*

REPAIRMAN <i>83</i>	PROOF	CLEAN <input checked="" type="checkbox"/>	TEST <input checked="" type="checkbox"/>	TARGET <i>Miller</i>	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/92