

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER R 94-00479

INITIAL CUSTOMER ORDER NO.

FFS

DATE RECEIVED 01/03/94 DATE OPENED 01/05/94 DATE CODE KN 5-93 SERIAL NUMBER S6233971 NEW SERIAL NUMBER MODEL AND GRADE 700 338 WIN MAG/SS/BDL ACCESSORIES W/STUDS

FROM:

DALLEY, BILL
4325 WEST 14TH ST. ROAD
GREELEY CO 80634

SHIP TO:

DALLEY, BILL
4325 WEST 14TH ST. ROAD
GREELEY CO 80634

CUST NO: 089968 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059015

WRITE

FROM DATE

ESTIMATED

2-10-94

VIA

UPS

GUN CONDITION

- NEW
- LIGHTLY WORN
- WORN
- VERY WORN
- UNREPAIRABLE
- MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN AMMO FUNCTION FINISH ACCURACY FIT INSPECT

CYCLE	11	*R1				
TRIGGER GROUP	<i>Will Not Load</i>				F1	F1
BOLT ASSY.					F1	F2
BARREL ASSY.					F3	F3
REC. ASSY.					F4	F4
WOOD			G1	G2	F5	F5
METAL			G2			

MAIN FAULT

Upon receipt, unable to duplicate customer concern. However, observation revealed that at 3 trigger adjustment screws have been tampered with. Called customer, he stated that the concern happened before he was given the trigger all adjustment in an attempt to correct.

PARTS

*TP - 2 1/4 lbs removed below min. spec.
SL - .014*

COMMENTS

*Agreed to replace component trigger screws and test rifle in gallery to good result.
Rifle now - reg. 5/93*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>RBS</i>					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/0