

RECEIVING AND ESTIMATING REPORT ✓

COMMENTS					
INITIAL PS	CUSTOMER ORDER NO. 5816				
DATE RECEIVED 11/21/91	DATE OPENED 01/29/91	DATE CODE CC 4-82	SERIAL NUMBER B6382158	MODEL AND GRADE 700 25-06 BDL	ORDER R 91-0290
ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS					

FROM: DANNYS PAWN & SPORTING 300 S BROADWAY MCALLEN TX 78501	SHIP TO: DANNYS PAWN & SPORTING 300 S BROADWAY MCALLEN TX 78501
---	--

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED 2-6	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST *rifle sometimes fires when bolt is closed*

MAIN FAULT *Cannot duplicate complaint. However, trigger assembly contaminated with a sticky substance; internal trigger parts are not moving freely. In addition, trigger assembly has been improperly adjusted outside factory - 1) insufficient over-travel 2) insufficient sear engagement. Trigger pull O.K. at 4 pounds - sear lift P.L. at 0.12". Rifle has not been properly maintained.*

Send repair quote for new trigger assembly but ± brownal price as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
BWT					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE