

P.I. \_\_\_\_\_ GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 BDL

GENERAL CONDITION: GOOD - WELL USED R #: 06337

OUTSIDE WORK: ST. CR SHORTENED, PROVISIONAL GLASS- DATE: JUNE 29, 1983

BEADED, SIGHTS REMOVED FROM: HARTWELL GARMENT CO.  
HARTWELL, GA. 30643

FIRED AMMO TYPE: UNKNOWN

& CONDITION: \_\_\_\_\_ GUN #: 26647268

PROOF: ✓ INSP.: ✓ TEST: ✓ CODE: W.D. 8-78

HEADING: \_\_\_\_\_ GA./CAL.: 7MM REM MAG

BREACH OPENING: \_\_\_\_\_ CHECKED BY: RICHARD JACKSON

RECOIL SHOULDERS: \_\_\_\_\_ APPROVED: [Signature] 6/29/83

CHAMBER: \_\_\_\_\_ APPROVED: [Signature]

TEST: \_\_\_\_\_ APPROVED: [Signature]

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

EXAMINATION OF THE FIREARM SHOWED NO DIMENSIONAL DEFECTS ON ANY OF THE PARTS.

COMPLAINT: GUN FIRED UPON RELEASING THE SAFETY, AS PER THE CUSTOMER, CAUSING DAMAGE TO A PICK UP TRUCK

INCIDENT: \_\_\_\_\_

COMMENTS: COULD STORAGE AND ADDITIONAL TESTS CONDUCTED COULD NOT DUPLICATE THE INCIDENT. HOWEVER, SEVERAL STEEL CHIPS WERE FOUND IN THE TRIGGER HOUSING THAT COULD HAVE POSSIBLY BEEN FROM THE FACTORY. BASED ON THESE FINDINGS, THE POSSIBILITY EXISTED THAT A CHIP COULD HAVE CAUSED THE INCIDENT.