

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-03195

INITIAL CUSTOMER ORDER NO.

JJM	DATE RECEIVED 01/20/92	DATE OPENED 01/27/92	DATE CODE RF 11-85	SERIAL NUMBER B6756272	NEW SERIAL NUMBER	MODEL AND GRADE 700 270	MTN
-----	---------------------------	-------------------------	-----------------------	---------------------------	-------------------	----------------------------	-----

FROM: DELOACH, JOEL K
RT 1 BOX 101
HAMPTON TN 37658

SHIP TO: DELOACH, JOEL K
RT 1 BOX 101
HAMPTON TN 37658

CUST NO: 056979 C.O.D.

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED 2-18-92	VIA UPS
CONDITION						REPAIR CHARGE
NEW						EXCISE
SLIGHTLY WORN						TAX
WORN						INSURANCE
VERY WORN						UPS
UNREPAIRABLE	PARCEL POST	TOTAL				

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
LT ASSY.	<i>Not firing properly - firing of safe</i>					F2
RREL ASSY.		B4		D1	E3	F3
C. ASSY.	<i>firing 5 or 6 seconds after pulling trigger</i>					F4
MOD			C1	D3	E5	F5
TOTAL			C2			

NO FAULT *Trigger assembly is contaminated with a gummy substance. Internal trigger parts not moving fully nor properly. Gun - Safety can be checked to each plate of trigger assembly. It has not been properly maintained. Trigger pull 5 Pounds, read left 0.12"*

COMMENTS *Offer to clean present trigger assembly, if possible. If not possible, offer replacement assembly at 1/2 regular cost, as a gesture of good-will.*

REPAIRMAN <i>DE</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

01609K REV. 8/81