

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 09/26/90	DATE OPENED 10/05/90	DATE CODE AA 3-80	SERIAL NUMBER A3200135	MODEL AND GRADE 700 30-06 BDL		ORDER R 90-258	
ACCESSORIES SLING STRAP		W/STUDS		W/SWIVELS		SCOPE BASE	
L/REAR SIGHT							

FROM: DENNIS COMPANY 115 S 4TH ST ELMA WA 98541	SHIP TO: DENNIS COMPANY 115 S 4TH ST ELMA WA 98541
---	--

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED 10-12-90	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST: *Gun goes off by itself.*

MAIN FAULT: *Targ assembly contaminated with sticky-gummy residue. Internal parts of target assembly not moving freely - rear safety cam & stuck to back plate of target assembly - as result, bolt cannot be inserted into action because stuck rear safety cam. Rifle has not been properly maintained.*

PARTS: *Send repair quotation for new target assembly at 1/2 normal price - the present assembly cannot be properly cleaned.*

REPAIRMAN <i>RBA</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY