

WORKING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-27164

CUSTOMER ORDER NO.

ATTN ED JOY

118362

DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/11/92	DK 9-90	B6886666		700 243 FS

W/STUDS SCOPE BASE L/SIGHTS

DENNIS HARDWARE
1 GRAVOIS RD
FENTON

Dennis
UNABLE TO DUPLICATE S.C. 10/83 .01" #
T.P 3 1/2
TRIG ASSY ADJ. OUTSIDE OF FACTORY
REPLACE TRIG ASSY FULL PRICE
NO SEALANT / BRIGHT MARKS ALL
SCREWS MILLERS HOME STATE
CHECK SET-UP
AS OPTION TO CUSTOMER
Martin

ACCOUNT NUMBER N/C

WRITE

ION

WORN

ORN

AIRABLE

D

GROUP	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
	A1	B1				
		B2			E1	F1
		B3			E2	F2
SSY.		B4		D1	E3	F3
		B5		D2	E4	F4
			C1	D3	E5	F5
			C2			

Unable to duplicate customer concern.
Inspection revealed trigger assembly adjusted outside of factory
to the point of trigger slipping from remaining adjustment screw
adjust. Trigger Pull 3 1/2 lbs

COMMENTS

Repair trigger assembly complete
at 1/2 normal replacement cost, as
gesture of good will

Clear trigger
Go ahead per Ken Cator phone 3/1

REPAIRMAN	PROOF	CLEAN	TEST	TARGET
<i>ASE</i>				
GALLERY TESTER	DATE	DATE	DATE	DATE

OFFICE COPY

RD6