

Dennis      unable To Duplicate 12/29  
T.P. # / S.L. .006  
Trigger Has Been Adjusted Outside  
Of Factory - No Force On Front Of  
Connector Brown Residue Is  
Evident On B. S. Release  
Gun Condition Poor - Witness  
The Rust - Charge For Replacement  
→ must