

RECEIVING AND ESTIMATING REPORT

DATE RECEIVED: 01/23/90 DATE OPENED: 01/23/90 DATE CODE: 000 SERIAL NUMBER: 1200 MODEL AND GRADE: 200 20MM MAG BDL ORDER: R

ACCESSORIES: 7 STUDS SCOPE BASE L REAR SIGHT

FROM: DAVID D'ISIDORO RD 1 BOX 201 SMOCK PA 15480

SHIP TO: DAVID D'ISIDORO RD BOX 201 SMOCK PA 15480

ACCOUNT NUMBER: _____ ACCOUNT NUMBER N/C: _____ PROM. DATE: _____ ESTIMATED: _____ VIA: UPS



REPAIR CHARGE: _____ TAX: _____ INSURANCE: _____ UPS: _____ PARCEL POST: _____ TOTAL: _____

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST: "It has a delayed action when fired and it discharges when the bolt is closed".

MAIN FAULT: Customer's complaint was duplicated with rifle in as-received condition. Subsequent disassembly of rifle revealed semi-soft cam sticking to housing side plate. Inside of assembly contaminated with gummy sticky residue (also present on bolt stop).

PARTS: 1) Per phone call to customer 1/23/90 - replace trigger assembly at no-charge, as good-will gesture
2) Charge \$10.00 handling and return shipping
1/23/90
JLD

DEPARTMENT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88