

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: NEW R # : 002678

OUTSIDE WORK: No DATE: 2-2-72

FROM: BILL DOTSON'S INC.

FIRED AMMO TYPE: - DECATUR, ILL.

& CONDITION: _____ GUN # : 6294075

PROOF: R.E.P.-A INSP.: 9 TEST: 13 CODE: XS = 12/69

HEADING: O.K. GA./CAL.: 270 WIN.

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER PULL 6LBS., ENGAGEMENT .020, TRIGGER BIND IS NOTICEABLE. IN DIS-ASSEMBLING THE TRIGGER HAS WHAT APPEARS TO BE DRIED STEEL GUARD ON THE SIDES CAUSING IT TO BIND.

COMPLAINT: "WHEN BOLT IS PUT IN ALL THE WAY THE GUN WILL GO OFF"

INCIDENT: FOLLOW DOWN

COMMENTS: THE SLUGGISH TRIGGER PROBABLY FAILED TO RETRACT RESULTING IN A FOLLOW DOWN MALFUNCTION.