

WORKING ESTIMATE REPORT 8-9000

2-19-81  
 GENERAL CONDITION: FAIR MODEL: 600  
 SERIAL NO.: STOPS ADDED. SIGNS REMOVED S.F.: 2423  
 MAKE AND TYPE: NOT KNOWN FROM: GLAN R. DOWLING  
 & LOCATION: \_\_\_\_\_ A-70 T.K.  
 MAKE: \_\_\_\_\_ SER. #: 6695076  
 MAKE: \_\_\_\_\_ YEAR: \_\_\_\_\_ TEST: \_\_\_\_\_ CODE: CY-4-74  
 MAKE: \_\_\_\_\_ OR \_\_\_\_\_ CAL./CAL.: 243  
 MAKE OPERATOR: \_\_\_\_\_ OR \_\_\_\_\_ CHECKED BY: M. HARDY  
 MAKE SERIALS: \_\_\_\_\_ OR \_\_\_\_\_ APPROVED: 204 10/2/81  
 CHECKER: \_\_\_\_\_ OR \_\_\_\_\_ APPROVED: 241 10/2/81  
 TEST: \_\_\_\_\_ APPROVED: P.H. 11/2/81  
 COMMENTS: (Damage, Breaks, Old Style) APPROVED: MAN/2/81

OLD STYLE FIRE CONTROL. CAM SURFACE  
ON BOLT HANDLE UPSET. NO SEAL ON OSEA DRAW STOP  
STOCK SPLIT LEFT FRONT BOL GROOVE

REMARKS: DISCHARGED WHILE LOCKING (RECEIVER)?

REMARKS: Gun involved in recall program. Gun  
may possibly be fired when safety & trigger  
are manipulated.