

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-27027

INITIAL CUSTOMER ORDER NO.

JUM 1735

DATE RECEIVED 12/03/93 DATE OPENED 12/13/93 DATE CODE EV 10-79 SERIAL NUMBER A6838496 NEW SERIAL NUMBER MODEL AND GRADE 700 7MMAG BDL

ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS

FROM:

[Signature]

DUFFY'S GUN ROOM
FALLS 7 BLACK ROCK ROADS
SPARKS MD 21152

SHIP TO:

DUFFY'S GUN ROOM
FALLS 7 BLACK ROCK ROADS
SPARKS MD 21152

CUST NO: 002317 C.O.D.

ACCOUNT NUMBER ACCOUNT NUMBER N/C PROM. DATE ESTIMATED 1-7 VIA UPS

- NEW
- LIGHTLY WORN
- WORN
- VERY WORN
- UNREPAIRABLE
- MARRED

REPAIR CHARGE 25.00
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Unable to duplicate customer concern. Examination of the 1979 rifle revealed rust on action, trigger assembly and ground pins. Also action ground nut rust and ground study substance. No ammunition.

COMMENTS

Replace copper trigger pins. Clean action, replace ground pins w/ 1/2 normal replacement cost. in future if good work.

REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

[Signature]

OFFICE COPY

RD6925 REV 11