

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-21149

INITIAL FPS	CUSTOMER ORDER NO. 33145						
DATE RECEIVED 10/07/92	DATE OPENED 10/13/92	DATE CODE OD 7-83	SERIAL NUMBER B6470503	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	BDL	
ACCESSORIES W/STUDS		SCOPE BASE					

FROM:

DUNBARS GUN REPAIR INC
509 1/2 UNION STREET
SPARTANBURG SC 29301

SHIP TO:

DUNBARS GUN REPAIR INC
509 1/2 UNION STREET
SPARTANBURG SC 29301

CUST NO: 006084 ILION L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION <input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED						REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	release
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Sent to J Steff
 Cannot duplicate complaint. However disassembly of trigger assembly and underneath receiver are identical with group. Inside of trigger assembly contaminated with dirt and oil. Even in above condition, the rifle could not be made to malfunction.
 Trigger pull 4.5 pounds; rear-lift 2.11"

PARTS	COMMENTS	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PAT
	1) Clean excessive oil off barrel of receiver 2) After following operation, a) clean & reassemble trigger assembly to install new trigger assembly at normal cost, as a gesture of good will, if that will better our confidence in rifle 3) Check new trigger guard assembly at normal cost, as good will gesture	OT					
		GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV