

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 ADL

GENERAL CONDITION: NEW R # : 001648

OUTSIDE WORK: SCOPE MOUNTED, SWIVELS & DATE: 1-26-72

RECOIL PAD FITTED. FROM: DUNN'S S&B GOS. INC.

FIRED AMMO TYPE: - PEVELY, MISSOURI

& CONDITION: \_\_\_\_\_ GUN # : 332321

PROOF: R.E.P. ASSEMBLER P INSP.: D TEST: 49 CODE: BL = 1/64

HEADING: O.K. GA./CAL.: 3006 CAL.

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_

CHAMBER: O.K. APPROVED: \_\_\_\_\_

TEST: NO APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

NO DAMAGED, BROKEN COMPONENTS. GEAR-CONNECTOR

ENGAGEMENT .010 (MIN. = .020) TRIGGER PULL = 3 1/2 (MIN. = 3 LBS.)

TRIGGER CLEARANCE ON CONNECTOR 1.087 M/D = 1.080

CONNECTOR CLEARANCE ON TRIGGER 1.073 M/D = 1.076

(.014 CLEARANCE WHERE .007 IS MAX.)

COMPLAINT: FIRES WHEN SAFE IS RELEASED

INCIDENT: CONNECTOR FAILS TO RETRACT.

COMMENTS: THE EXCESSIVE CLEARANCE BETWEEN CONNECTOR

AND TRIGGER ALLOWS THE CONNECTOR TO CREEP UP INTO

AN INTERFERENCE POSITION WHERE IT FAILS TO RETRACT

WITH THE SAFETY ON. WHEN THE SAFETY IS

RELEASED THE FIRING PIN FOLLOWS DOWN.