

RECEIVING AND ESTIMATING REPORT ✓

TITLE		CUSTOMER ORDER NO.		COMMENTS			
PS							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
4/24/91	04/25/91	LI 2-88	C6231502	700 308 WIN POL		R 91-09844	
ACCESSORIES		SCOPE BASE					
W/STUDS							

FROM: TPR. DYWINSKI, LEON SFI NEW YORK STATE POLICE 4525 W SAILE DR BATAVIA NY 14020	SHIP TO: TPR. DYWINSKI, LEON SFI NEW YORK STATE POLICE 4525 W SAILE DR BATAVIA NY 14020
--	---

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

UN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST: *"When the safety is on the bolt is able to be cocked. When the safety is released the firing pin goes forward"*

MAIN FAULT: *As received, the firing pin followed-down when the bolt was closed. Disassembly revealed the trigger assembly was rusted from unknown cause, causing the internal trigger parts to not move freely.*

REMARKS: *Replace trigger assembly of no-charge, as gesture of good-will.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>AB</i>					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90