

000-37

3-3 221-226

P.I. 210 GUN EXAMINATION REPORT NUMBER: 210 MODEL: 700-202

GENERAL CONDITION: FAIR R # : 10686

OUTSIDE WORK: REAR SIGHT REMOVED DATE: 3-25-80

SCORE CASE ADDED FROM: 10686 322125

FIRE ARMO TYPE: NOT KNOWN MES 302

& CONDITION: _____ GUN # : 652477

PROOF: REM DISP.: 9 TEST: 97 CODE: 211-2-72

READING: OK GA./CAL.: 2536

BREECH OPENING: OK CHECKED BY: 10-2-80

RECOIL SHOULDERS: OK APPROVED: GM 4/23/80

CHAMBER: OK APPROVED: 10686 4/23/80

TEST: _____ APPROVED: 10686 4/23/80

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 10686 4/23/80

SLIGHT MARKS ON STOCK

BRIGHT METAL MARKS ON BR

COMPLAINT: FIRED WHEN SAFETY WAS UP TO 150

INCIDENT: _____

COMMENTS: Lead diff. 0095" Tracer pull 4", Passed
Trick Test.

The control adjustment screws visible adjacent
inside of Remington and resealed with red sealants.

Unable to duplicate customer complaint.