

Setup file

REPAIR GUN INQUIRY FUNCTION: E (N)EXT (P)REV (I)NQ (E)XACT 07/25/90
ENTER REPAIR NUMBER -----> 9018689 16 07 30
B6719276
FROM: (CUST NUM: 025562) EGGERT MODEL: 700
EGGERT, TROY GA/CAL: 0030-06
19319 OXFORD STREET TYPE: BDL
ACCESSORIES: W/STUDS
HARD CASE

ELK RIVER MN 55530
SHIPPED TO:

612-493-2749

DATE CODES: PF 6-85
OTHER ACCESSORIES:

COMMENTS: HARD CASE RETURNED 7-25-90

DATES:		TO	FROM		
RECEIVED	06 25 90	GALLERY	07 16 90	07 17 90	ENTERED BY: JJM
OPENED	07 02 90	PROD SERV	00 00 00	00 00 00	REPAIRMAN: RF
ESTIMATED	07 13 90	TAG GUNS	00 00		TYPIST:
PROMISED	00 00 00	REJECTED	00 00		CORRESPONDENT:
REPAIRED	00 00 00	CASH RECEIVED:\$		0.00	
SHIPPED	07 23 90				
BILL TYPE	N/C				

PF1 = VIEW DETAIL

REPAIR NUMBER: 9018689 NO CHARGE EST/LETTER LSTD 07/25/90
CUSTOMER NAME: EGGERT, TROY 16 07 41

REQUEST: MISFIRED, SCRATCHED AND MARRED BOLT. STOCK SCRATCHED.
MAIN FAULT: FRONT GUARD SCREW TOO LONG CAUSING BOLT NOT TO FULLY CLOSE.
BOLT SHOWS ABNORMAL WEAR FOR CONDITION OF RIFLE, WE WILL REPLACE IT. WE CANNOT BE RESPONSIBLE FOR A STOCK SCRATCHED OUTSIDE OF OUR CONTROL.

PARTS:	\$	0.00	1	92897 BOLT ASSEM (BDL 270 - 30-06 MAX)
LABOR:	\$	0.00		CHAMBER EXTREMELY RUSTY, MUST BE KEPT CLEAN AND LIGHTLY
	\$	0.00		OILED
	\$	0.00		POLISH CHAMBER
	\$	0.00		ADJUST FRONT GUARD SCREW
	\$	0.00		SEND OWNERS MANUAL
	\$	0.00		PROOF, CLEAN, TEST

CLEAR = RETURN
NO MORE DATA AVAILABLE FOR THIS REPAIR