

Polymerite Quality Components Inc.  
Oval Products Division  
5500 N. Miami 48-42157

June 30, 1980

Dear Sir:

I am writing in response to your letter regarding the repair of my Remington firearm which I received the week of April 1, 1980. I feel that after reading your letter you did not understand my intentions and its taken up to now for me to get over my anger to respond. In 1981 I purchased a supposedly new M-100, 30-06 Remington rifle, this rifle however did not come with a owner's manual or warranty certificate but did come with scratches and dents and not being able to find another rifle like this one in the Twin Cities I decided not to question this one. That fall while firing this firearm for the first time my rifle dry-fired two rounds out of ten shots and by the same reoccurring problem the next fall dry-firing three rounds out of twenty. In the following year I brought my firearm into be serviced by one of your reputable service centers but when my rifle was returned the problem of dry-firing was not resolved and there was severe