

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 94-12890

INITIAL  
FJB

CUSTOMER ORDER NO.

DATE RECEIVED 04/12/94	DATE OPENED 04/13/94	DATE CODE WP 8-67	SERIAL NUMBER 298807	NEW SERIAL NUMBER	MODEL AND GRADE 700 270	BDL
ACCESSORIES W/STUDS		SCOPE BASE				

FROM:

EKEY, ROBERT  
719 SOUTH SIXTH AVE  
BOZEMAN

MT 59715

SHIP TO:

EKEY, ROBERT  
719 SOUTH SIXTH AVE  
BOZEMAN

MT

59715

CUST NO: 095854 C.O.D.L.

ACCOUNT NUMBER 063103	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
--------------------------	--------------------	--------------------------------	------------	-----------	------------

GUN CONDITION

- NEW
- LIGHTLY WORN
- WORN
- VERY WORN
- UNREPAIRABLE
- MARRED

REPAIR CHARGE	20
EXCISE	
TAX	
INSURANCE	
UPS	8
PARCEL POST	
TOTAL	28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	<i>Two gun has misfired twice when slowing the bolt</i>					
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.					E2	F2	
BARREL ASSY.		B4		D1	E3	F3	
REC. ASSY.		B5		D2	E4	F4	
WOOD			C1	D3	E5	F5	
METAL			C2				

MAIN FAULT *Mfg 8-67 unable to duplicate customer problem as rec'd. Trigger flunked and sear was gummed up with shell like residue. Exchange Trigger Assy. at special price, as gesture of good will and to restore customer confidence in rifle.*

PARTS	<i>Trigger Assy Complete</i>	COMMENTS	<i>Trigger pull measured 2 1/2 lbs pull to slide. sear left was .010 Also, some rust on underside of bolt.</i>			
-------	------------------------------	----------	--	--	--	--

REPAIRMAN TAL	PROOF	CLEAN ✓	TEST ✓	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD8925 REV. 1/94