

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: Good R #: 03978
OUTSIDE WORK: NO DATE: 3-1-71
FROM: ERBACHERS SPTS. CNTR.
FIRED AMMO TYPE: - MADISON, OHIO.
& CONDITION: _____ GUN #: 278328
PROOF: R.E.P. INSP.: D TEST: 87 CODE: CP-4/67
HEADING: O.K. GA./CAL.: 7MM MAG.
BREECH OPENING: - CHECKED BY: C.P.
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO COMPONENT DAMAGE OR BREAKAGE,

COMPLAINT: "FIRED TWO TIMES WHEN CLOSING BOLT."

INCIDENT: FOLLOW DOWN

COMMENTS: TRIGGER CONNECTOR-SEAR ENGAGEMENT .025. THE TRIGGER ETC. WAS FOUND TO BE COATED WITH A HEAVY-GREASE-LIKE LUBRICANT WHICH WOULD CAUSE TRIGGER RETRACTION TO BE ERRATIC. THIS APPARENTLY HAPPENED TO THE CUSTOMER-TRIGGER DID NOT RETRACT AND WHEN THE BOLT WAS CLOSED THE FIRING PIN FOLLOWED DOWN.