

M/600 Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 600

GENERAL CONDITION: GOOD R # : 10844

OUTSIDE WORK: TRIGGER HOUSING ADJUSTMENTS DATE: 5-17-71

UNSEALED & CHANGED. FROM: JOSEPH D. FUDY

FIRED AMMO TYPE: _____ KINSTON, N.C.

& CONDITION: _____ GUN # : 80913

PROOF: R.E.P. INSP.: 76 TEST: 13 CODE: CP-4/67

HEADING: O.K. GA./CAL.: 243

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN, DAMAGED COMPONENTS. EVIDENCE OF DRIED LUBRICANT INSIDE TRIGGER HOUSING.

COMPLAINT: "IF COCKED WITH SAFETY ON AND TRIGGER IS PULLED WHEN THE SAFETY IS RELEASED IT WILL FIRE, SOMETIMES IT WILL NOT COCK ON CLOSING."

INCIDENT: FOLLOWS DOWN

COMMENTS: IT APPEARS THAT THE DRIED LUBRICANT CAUSED THE TRIGGER AND SEAR TO REMAIN IN FIRED POSITION AFTER FIRING.