

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

JAN 12 1987

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

R.H. POTTER

To A.S.

Mr. Charles E. Fenner *R-86-23607* December 30, 1986
541 Cushing Ct.
Brookings, Oregon 97415

*1-14-86 Pls put in new trig. assembly
+ ship ASAP (prepaid) N/C*

Dear Mr. Fenner:

Examination has been completed on your Mohawk 600 rifle, serial #6390843.

The Mohawk 600 rifle series with a letter prefix serial number, like your rifle, has never been under recall as these firearms, feature a modified fire assembly which is different from the trigger assembly associated with the recalled Model 600 series firearms. Therefore, your rifle is not under recall.

Our expert examined your rifle in general and its fire assembly in particular and found no defects. The sear lift measured .009" and the trigger pull tested also repeatedly at 5 pounds. Both these specifications are well within Remington qualifications. The trigger assembly was also examined for excessive lubrication which was not present.

Repeated attempts to duplicate your incident failed. The only way the rifle was made to fire was when the safety was pushed to the fire position and the trigger pulled. Based upon these findings, Remington cannot be responsible for your truck damage or for replacing your rifle with a new Model Seven.

We'd like to return your rifle, prepaid, to your home address in its present condition. However, as a no charge gesture of goodwill and so that your confidence in the firearm can be completely restored, we will install a new trigger assembly prior to shipment, if you so advise by phone or mail.

Y-30 O'Brien 1/8/87

We regret you experienced the unfortunate situation, Mr. Fenner, but rest assured your firearm is, and will be, in 100% safe operating condition.

Thank you for giving us this opportunity to examine your rifle and to report our findings to you. We wish you every hunting and shooting success in 1987 and beyond.

Sincerely,

R.H. Potter
R. H. Potter, Supervisor
Product Service

RHP:cm