

d 88

DON'T SAY IT—WRITE IT

To _____

Date _____

From _____

Excessive vertical play of connector to trigger.

Failed screenwire test. Trigger pull 2.1 #

Did appear to be adjustment of engagement adjusting screw.

SEAR - connector engagement = .012 inch

"YOUR SAFETY ATTENTION MEANS ACCIDENT PREVENTION"