

# RECEIVING AND ESTIMATING REPORT

*STEKO*

CUST NO: 048525 C.O.D  
CUSTOMER ORDER NO.

COMMENTS

ID	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	BDL/VAR	ORDER
0/91	09/04/91	XC 12-82	B6432968	700 22-250		R 91-17382

SERIES W/STUDS

NAME: FISHER, WILLIAM H RTE 1 STAR RT 679 BOX 417 FINCASTLE VA 24090 USA	SHIP TO: FISHER, WILLIAM H RTE 1 STAR RT 679 BOX 417 FINCASTLE VA 24090 USA
--	--

QUANTITY	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					9/20/91	UPS

R CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
----------	-----	-----------	-----	-------------	-------

CONDITION:  NEW  SLIGHTLY WORN  VERY WORN  MISUSED  MARRED

OWNER'S REQUEST: *"Spd gun fired when loading. It won't stay cocked part of the time. I think there's a problem with the trigger assembly."*

FAULT: *Trigger assembly has been improperly adjusted outside of factory - adjust missing from adjustment screws. Trigger pull measured only 1 pound - trigger retention spring force is non-existent. Firing pin will follow down on bolt closing because of above condition 2) excessive web-travel. Spear left .015"*

*Send quote for new trigger assembly at 1/2 normal price, as good-will gesture.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>[Signature]</i>					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE